

Recall Quarterly Report**18V-667**

Manufacturer Name : Suzuki Motor of America, Inc.
NHTSA Recall No. / MFR Recall No. : 18V-667 /4009
Recall Subject : Power Steering Tensioner Pulley Damage
Owner Notification Beginning Date : NOV 09, 2018
Owner Notification End Date: NOV 09, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 25, 2019	2019-3	304	34	45	0
3	JUL 26, 2019	2019-2	304	29	45	0
2	APR 29, 2019	2019-1	304	27	45	0
1	FEB 08, 2019	2018-4	304	17	44	0

This Document Last Updated : OCT 29, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.