

Part 573 Safety Recall Report

21V-747

Manufacturer Name : Carson Trailer, Inc.

Submission Date : SEP 24, 2021

NHTSA Recall No. : 21V-747

Manufacturer Recall No. : Recall3



Manufacturer Information :

Manufacturer Name : Carson Trailer, Inc.

Address : 14831 S. Maple Ave

Gardena CA 90248

Company phone : 999

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2021-2021 CARSON CARRIERS

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : there is a possibility that the spindle nuts in the trailer axles were insufficiently torqued.

Production Dates : MAY 25, 2021 - JUL 15, 2021

VIN Range 1 : Begin : 4hxbu1622nc223061 **End :** 4hxbu1628nc223890 Not sequential

Description of Defect :

Description of the Defect : a certain number of spindle nuts were not torqued to prescribed standards

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : axle, tire or wheel failure may affect vehicle stability

Description of the Cause : improper torquing of spindle nut

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : Spindle Nut

Component Description : Spindle Nut retains the hub assembly in the spindle

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Terran Axle

Address : 1 Westbrook Corporate Center
Westchester Illinois 60154

Country : United States

Chronology :

Terran management made a formal determination that remedial field action was necessary.

Description of Remedy :

Description of Remedy Program : For axles that have been in operation on a moving trailer and experience vibration.

How Remedy Component Differs from Recalled Component : Remedy involves torqueing the spindle nut to prescribed standards

Identify How/When Recall Condition was Corrected in Production : Inspect each trailer axle and if spindle nut was insufficiently torqued, the spindle nut was torqued to prescribed standards.

Recall Schedule :

Description of Recall Schedule : when report get approved.

Planned Dealer Notification Date : SEP 30, 2021 - NOV 30, 2021

Planned Owner Notification Date : NR - NR

* NR - Not Reported