



Ford Motor Company
 Ford Customer Service Division
 P. O. Box 1904
 Dearborn, Michigan 48121 1904



771741667774

A/1/000001/1

December 2022



JOHN A. SAMPLE
 123 SAMPLE ST
 SAMPLE CITY, MI 12345-6789

***** IMPORTANT SAFETY RECALL *****

Safety Recall Notice 22S68 / NHTSA Recall 22V792

2023 E-450 Econoline

Your Vehicle Identification Number (VIN): XXXXXXXXXXXXXXXXXXXX

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue? On your vehicle, it may be possible the rotor/hub assembly bolt was improperly torqued.

What is the risk? This may result in a loss of wheel attachment during hard acceleration or hard brake application events, increasing the risk of a crash.

What will Ford and your dealer do? Ford Motor Company is working closely with its suppliers to produce parts for this repair. When parts become available, Ford Motor Company will notify you via mail to schedule a service appointment with your dealer for repairs to be completed free of charge (parts and labor). **Parts are anticipated to be available first quarter 2023.**

What should you do? When parts are available, Ford Motor Company will send a letter to inform you that parts are available and to contact your dealer to schedule a repair. Ford has not issued instructions to stop driving your vehicle under this safety recall. When parts are available, you should contact your dealer for an appointment to have your vehicle remedied as soon as practicable. If you do not already have a servicing dealer, you can access ford.com/support for dealer addresses, maps, and driving instructions. If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to [NHTSA.gov](https://www.nhtsa.gov). Reference NHTSA Safety Recall 22V792.

Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

NOTE: You can receive information about Recalls and Customer Satisfaction Programs through our FordPass App. The app can be downloaded through the App Store or Google Play. In addition there are other features such as reserving parking in certain locations and controlling certain functions on your vehicle (lock or unlock doors, remote start) if it is equipped to allow control.

Thank you for your attention to this important matter.

Ford Customer Service Division



Ford Motor Company
División de Servicio al Cliente de Ford
P. O. Box 1904
Dearborn, Michigan 48121



771741667774

A/2/000001/1

Diciembre de 2022



JOHN A. SAMPLE
123 SAMPLE ST
SAMPLE CITY, MI 12345-6789

***** CAMPAÑA DE SEGURIDAD IMPORTANTE *****

Aviso de Campaña 22S68 / Campaña 22V792 de la NHTSA

2023 E-450 Econoline

Número de identificación del vehículo (VIN): XXXXXXXXXX

Este aviso se le envía de acuerdo con la Ley Nacional de Seguridad de Tránsito y Vehículos Motorizados de los EE. UU.

Ford Motor Company ha determinado que existe un defecto relacionado con la seguridad de su vehículo, con el VIN que aparece más arriba.

Lamentamos esta situación y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su distribuidor, es ofrecerle servicio y apoyo de alto nivel.

- ¿Cuál es el problema?** Es posible que el tornillo del ensamble del rotor/maza de su vehículo se haya apretado incorrectamente.
- ¿Qué riesgo existe?** Esto podría traducirse en una pérdida de la unión de la rueda durante eventos de aceleración intensa o aplicación brusca del freno, lo cual aumenta el riesgo de choque.
- ¿Qué medidas adoptarán Ford y su distribuidor?** Ford Motor Company colabora estrechamente con sus proveedores para fabricar las piezas para esta reparación. Cuando estas estén disponibles, Ford Motor Company le avisará mediante correo para programar una cita de servicio con su distribuidor y así realizar las reparaciones sin costo alguno (piezas y mano de obra). **Se prevé que las piezas estarán disponibles el primer trimestre de 2023.**
- ¿Qué debe hacer?** Cuando las piezas estén disponibles, Ford Motor Company le enviará una carta para informarle la disponibilidad de estas y solicitarle que se comunique con su distribuidor a fin de programar la reparación.
- Para esta campaña de seguridad, Ford no ha emitido instrucciones de no manejar el vehículo. Cuando las piezas se encuentren disponibles, deberá ponerse en contacto con su distribuidor a fin de programar una cita para solucionar este problema lo más pronto posible.
- Si aún no tiene un distribuidor para realizar el servicio, puede acceder a ford.com/support para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.
- Si continúa con dificultades para reparar su vehículo en un tiempo razonable o sin cargo, le sugerimos que escriba al Administrador, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 o bien que llame sin cargo a la línea directa de seguridad vehicular al 1-888-327-4236 (TTY: 1-800-424-9153) o visite [NHTSA.gov](https://www.nhtsa.gov). Referencia: Campaña de seguridad 22V792 de la NHTSA.
- Tenga presente que: La ley federal exige que los arrendadores de vehículos que reciban este aviso de campaña envíen una copia del mismo al arrendatario en un plazo de diez días.**
- NOTA: Puede recibir información sobre las campañas y los programas de satisfacción del cliente a través de la aplicación FordPass. La aplicación se puede descargar a través de App Store o Google Play. Adicionalmente, existen otras funciones como reserva de estacionamientos en determinados lugares, además de control de ciertas funciones en el vehículo (bloqueo o desbloqueo de puertas, arranque remoto) si así está equipado para permitir el control.

Gracias por su atención en este asunto sumamente importante.

Ford, División de Servicio al Cliente