



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

July 29, 2024

Shaun Austin
Director Vehicle Safety Investigations
Hyundai Motor America
10550 Talbert Avenue
Fountain Valley, CA 92708

NEF-107ES
24V-562

Subject: Unintended Movement on Vehicle Startup

Dear Shaun Austin:

This letter serves to acknowledge Hyundai Motor America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HYUNDAI/GENESIS COUPE/2010-2013

Mfr's Report Date: July 25, 2024

NHTSA Campaign Number: 24V-562

Components:

ELECTRICAL SYSTEM:IGNITION:INTERLOCK/LOCKOUT

Potential Number of Units Affected: 12,612

Problem Description:

Hyundai Motor America (Hyundai) is recalling certain 2010-2013 Genesis Coupe vehicles. A return spring in the ignition lock switch may fracture, which can result in unintended vehicle movement when the vehicle is started in gear, without the parking brake applied.

Consequence:

Unintended vehicle movement can increase the risk of a crash.

Remedy:

Dealers will replace the ignition lock switch, free of charge. Owner notification letters are expected to be mailed September 23, 2024. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 266.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Hyundai Motor America's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement