



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 5, 2024

Mr. Sam Geser
CRA Manager
Daimler Trucks North America, LLC
4747 N Channel Ave
Portland, OR 97217

NEF-107ES
24V-569

Subject: Ground Connection May Overheat

Dear Mr. Geser:

This letter serves to acknowledge Daimler Trucks North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

THOMAS BUILT BUSES/SAF-T-LINER C2/2024-2025
THOMAS BUILT BUSES/SAF-T-LINER C2 JOULEY/2024-2025

Mfr's Report Date: August 1, 2024

NHTSA Campaign Number: 24V-569

Components:

ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 629

Problem Description:

Daimler Trucks North America, LLC (DTNA) is recalling certain Thomas Built Buses 2024-2025 Saf-T-Liner C2 and Saf-T-Liner C2 Jouley school buses. The ground cable for the air conditioning system may have been improperly installed and overheat.

Consequence:

An overheated ground cable can increase the risk of a fire.

Remedy:

Dealers will inspect and repair the ground cable connection, free of charge. Owner notification letters are expected to be mailed September 29, 2024. Owners may contact DTNA customer service at 800-745-8000. DTNA's number for this recall is F1008.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Daimler Trucks North America, LLC's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement