

**Daimler Truck
North America LLC**

Daimler Truck North America LLC
Warranty Campaigns Department
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone

DATE: 04/14/2025

TO: My Communication

SUBJECT: SAFETY RECALL NOTICE – STOP DELIVERY: F1018

On **March 25, 2025**, Daimler Truck North America (DTNA) filed a Defect Information Report (DIR) with the National Highway Traffic Safety Administration (NHTSA) and/or a Defect Information Notice (DIN) with Transport Canada (TC) informing the agencies of our intent to conduct a voluntary safety recall.

It is a violation of Federal law for a dealer or distributor to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. **Some of the vehicles subject to this "Stop Delivery Notice" may be in your *new* vehicle inventory.** Until further instructions are available, ***new* vehicles subject to this "Stop Delivery Notice" must be held and not be delivered to customers.**

DTNA strongly recommends that dealers and distributors remedy Recalls before selling used vehicles. For any used vehicle with an open recall not remedied before sale, DTNA requires that the dealer or distributor notify prospective buyers of the open recall.

Please ensure that registration information on vehicles subject to this recall is up to date to facilitate accurate owner notification.

Affected Vehicles in F1018:

Make	Model	Model Yr. Start	Model Yr. End	Prod. Start Date	Prod. End Date
Freightliner	108SD	2026	2026	01/21/2025	02/28/2025
Freightliner	114SD	2026	2026	01/17/2025	02/27/2025
Freightliner	Business Class M2	2025	2026	11/23/2024	02/28/2025
Freightliner	Cascadia	2026	2026	01/14/2025	02/28/2025
Western Star	47X	2025	2026	10/10/2024	02/28/2025
Western Star	49X	2025	2026	11/25/2024	02/21/2025

Problem: In the affected vehicles, a defect in the automatic emergency braking systems' software can apply the brakes during a vehicle-induced hard braking event without illuminating the brake lamps. This results in the inability to notify other drivers of the vehicle slowing in these

specific braking events, and in turn increasing the risk of crash.

Solution: Remedy software will have corrected parameters enabling the electronic path to illuminating brake lamps.

Owner Notification Mailing Schedule: 05/24/2025