



Service Bulletin

PRELIMINARY INFORMATION

Subject: Tire Learning Active Message on at Startup

Models: 2013 Cadillac ATS

Condition/Concern

Some customers may comment on a "Tire Learning Active" message appearing at startup.

Recommendation/Instructions

Engineering is aware of the condition and working on a service solution. Do not attempt any repairs at this time for this concern. This PI will be updated once repair information becomes available.

Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

ADDITIONAL SI KEYWORDS:

DIC Learn Start TPM

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION