



Service Bulletin

File in Section: -

Bulletin No.: PIC5643F

Date: June, 2013

PRELIMINARY INFORMATION

Subject: PQC Part Restriction - Electronic Power Steering (EPS) Gear Parts Restriction Ended

Models: 2012 Chevrolet Camaro ZL1
2013 Chevrolet Camaro Equipped with any V8 Engine (RPO LS3 or LSA or L99)

This PI was superseded to indicate the restriction has ended. Please discard PIC5643E.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Effective 6/21/13 the Electronic Power Steering (EPS) Gear will no longer be on restriction through the PQC.

Recommendation/Instructions

If it is determined that an EPS gear is necessary during repairs of the above listed vehicles, the parts are now available through GM Customer Care & Aftersales (CCA).

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.