

Audi of America, Inc.



Date: September 22, 2014

To: Audi Dealer Principal, Service Manager, and Parts Manager

From: Audi Product Compliance

Subject: Upcoming Update 3719  
ECM/TCM Software Update  
2015 A8 4.0L

Dear Audi Dealer Principal, Service Manager, and Parts Manager:

This communication is to inform you of upcoming Update **3719**.

**What vehicles are affected?**

There are 707 Audi vehicles affected in the U.S. by this Update.

Of the affected vehicles, the following are in dealer inventory:

New Vehicle Inventory: 707

**What is the issue?**

On Audi A8 vehicles with 4.0 ltr engines the shifting operation of the gearbox may feel uncomfortable or a slight engine hesitation may be felt

**What does the repair procedure involve?**

Update the ECM and/or TCM to the latest level.

**When will the Update be available?**

This Update will be visible in Elsa and ServiceNet on or about September 23, 2014.

Please refer to the Elsa campaign/action screen for confirmation of whether the Update applies to each specific vehicle. Additionally, this Update is posted on Elsa and ServiceNet for additional information and complete repair instructions.

Consistent with general Audi corporate policy governing Updates, Audi is not notifying consumers. (Updates differ from recalls and service actions; consumers are notified in writing of recalls and service actions.) Each vehicle should be completed when it is in to the dealer for maintenance or any other service visit. Dealer stock vehicles **cannot, however, be delivered** to consumers until the Update is completed.

To identify any vehicles in your inventory that are affected by this Update, please run the "New and CPO Inventory Open Campaign/Action Listing" report from the AIM system.

Please ensure that every affected vehicle gets the update before delivery to consumers. Your effort is integral in reaching the highest quality expectations of Audi customers.

Thank you for your cooperation and assistance in this important matter.

Audi of America, Inc.  
3800 Hamlin Road  
Auburn Hills, MI 48326  
+1 248 754 5000  
www.audiusa.com