

[Next Unread Message](#)**View Message**

**Sent on** 10 02 2014 **Expires on** 10 16 2014  
**From** Parts and Service Division  
**Subject** Request for Visit: 2012-2014 CR-V Parking Brake Indicator Inop

**To:** All Honda Service Managers/Advisors  
**From:** Technical Research & Support Group  
**RE:** Request for Visit: 2012-2014 CR-V Parking Brake Indicator Inop

This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda (AHM) is investigating certain 2012-2014 CR-Vs with a complaint of the parking brake indicator not illuminating when engaged. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to your attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. VIN must start with 2HK.
2. Both 2WD & 4WD are accepted.
3. First time complaint only.
4. No previous repair for this issue.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.