



Service Bulletin

PRELIMINARY INFORMATION

Subject: Drivers Power Or Memory Seat and/or Power Adjustable Pedals Inoperative (Inspect For Poor Terminal Tension)

Models: 2015 Cadillac Escalade Models
2015 Chevrolet Tahoe, Suburban
2015 GMC Yukon Models

This PI was superseded to update Models and Part Information. Please discard PIT5279.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some owners may comment of the driver's power seat or the memory seat functions are inoperative. Also, if the vehicle is equipped with adjustable pedals they will be inoperative. While performing diagnosis, check terminal tension at the left IP fuse block (X51L) connector X1 terminals 27 and 28, using the correct Diagnostic Test Probe listed in SI.

Recommendation/Instructions

If terminal tension is found to be poor, it will need to be replaced. The terminal is now available as a terminated lead, part number 19301761, which is available through CCA parts.

Parts Information

| Part Number | Description | Qty |
|-------------|-----------------|-----------|
| 19301761 | WIRE ASM-SPLICE | As Needed |

Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin 10-00-89-005 for warranty information on wire/connector repairs.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION