

[Next Unread Message](#)

View Message

| | | | | | | | |
|----------------|---|----|------|-------------------|----|----|------|
| | | | | | | | |
| Sent on | 04 | 29 | 2016 | Expires on | 05 | 13 | 2016 |
| From | Parts and Service Division | | | | | | |
| Subject | Request for Visit: 2014-2016 MDX Noisy Front Blower Motor | | | | | | |

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Visit: 2014-2016 MDX Noisy Front Blower Motor

This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this i/N message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2014-2016 MDXs with a customer complaint of a noisy front blower motor. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. First time complaint only.
2. Must confirm rust on the lower part of the blower motor.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.