

MODEL: Karma Revero**Revised: November 2017****TITLE: TPMS TOOL USE**

APPLICABILITY: MY17 and MY18 Revero

MARKET REGION: North America

PURPOSE: This document will be used as a reference guide for technicians on how to set up and use the special service TPMS tool. This is used to locate and learn the Sensor IDs at each wheel. This can be done independently of Karma Sync.

Tools Required:

- C161102100500 - ATEQ VT56
- The included OBDII interface module and LAN cable to connect to the hand-held tool
- Tire pressure gauge



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero

Revised: November 2017

TITLE: TPMS TOOL USE

1. Review the tire placard (fig. 1a) for the correct inflation pressures (fig 1b , Item 1 on driver door b-pillar)

- Verify the current pressures and adjust to specification with a suitable tire gauge (fig 1c)

TIRE AND LOADING INFORMATION RENSEIGNEMENTS SUR LES PNEUS ET LE CHARGEMENT			
SEATING CAPACITY NOMBRE DE PLACES	TOTAL 4	FRONT AVANT 2	REAR ARRIÈRE 2
THE COMBINED WEIGHT OF OCCUPANTS AND CARGO SHOULD NEVER EXCEED 300 KG OR 660 LBS. LE POIDS TOTAL DES OCCUPANTS ET DU CHARGEMENT NE DOIT JAMAIS DEPASSER 300 KG OU 660 LB.			
TIRE PNEU	SIZE DIMENSIONS	COLD TIRE PRESSURE PRESSION DES PNEUS A FROID	SEE OWNER'S MANUAL FOR ADDITIONAL INFORMATION VOIR LE MANUAL DE L'USAGER POUR PLUS DE RENSEIGNEMENTS
FRONT / AVANT	255 / 35 R22	40 PSI / 275 kPa	
REAR / ARRIÈRE	285 / 35 R22	36 PSI / 248 kPa	
FRONT / AVANT	245 / 40 R21	35 PSI / 241 kPa	
REAR / ARRIÈRE	265 / 40 R21	38 PSI / 262 kPa	
SPARE / DE SECOURS		NONE / AUCUN	

C149962001200

fig 1a




fig 1b



fig 1c

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero

Revised: November 2017

TITLE: TPMS TOOL USE

2. Power on the ATEQ VT56 use the red button below.(fig 2)
- Ensure settings are correct before starting learn procedure
 - Access the settings by pressing the “C” button on the tool
 - Select “Sensor” menu and press “OK” button on tool



fig 2

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero

Revised: November 2017

TITLE: TPMS TOOL USE

3. In the “Sensor” menu select “manual” and press “OK” (fig 3a)



fig 3a

- Set this to “Karma” -press OK (fig 3b, 3c, 3d)

- select Revero, then select 2017

Note: 2018 option is not currently set, however it does use the same hardware for TPMS, the 2017 option will function as normal.




fig 3b




fig 3c




fig 3d

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero**Revised: November 2017****TITLE: TPMS TOOL USE**

8. Begin procedure at LF (left front) tire valve stem (fig 7a)

- Press green trigger button to activate sensor and again to begin
- The TPMS tool will emit an audible beep and vibrate when sensor is activated
- Continue procedure to RF, RR and LR wheels



fig 7a

The tool lists the order of sensors to be scanned.

MODEL: Karma Revero

Revised: November 2017

TITLE: TPMS TOOL USE

- The tool picks up the sensor signals from the *tire* side. Make sure the tool is on the tire for best reception as shown (fig 8a - 8c)



fig 8a



fig 8b

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero

Revised: November 2017

TITLE: TPMS TOOL USE

- When all 4 sensors are correctly read out the ID, tire pressure, frequency, degrees Fahrenheit and sensor battery status will be displayed (fig 8c)



fig 8c

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero

Revised: November 2017

TITLE: TPMS TOOL USE

9. Prepare ATEQ OBDII interface with LAN cable (fig 9a)



fig 9a

- Connect interface to bottom of ATEQ VT56 at LAN interface port on bottom of tool (fig 9b)



fig 9b

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero**Revised: November 2017****TITLE: TPMS TOOL USE**

10. Follow the prompts. (fig. 10a) press “OK” after the tool successfully connects



fig 10a

- Have the vehicle fully asleep before connection
- Connect OBDII interface to OBDII port (fig 10b)



fig 10b

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero**Revised: November 2017****TITLE: TPMS TOOL USE**

- Place vehicle into Ready mode (fig 10c)



fig 10c

- A successful connection to the vehicle will show the indicated graphic on the tool.
(fig. 10d)



fig 10d

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero

Revised: November 2017

TITLE: TPMS TOOL USE

11. Use the arrow keys to highlight the OBDII connector icon, and press “OK” to select (fig 11)



fig 11

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

MODEL: Karma Revero

Revised: November 2017

TITLE: TPMS TOOL USE

12. ECU relearn will prompt "ECU Relearn"

- Select Green checkmark and press "OK" (fig 12a)
- It will display "Successful Transfer"
There is no second prompt to press "OK," however, press "OK"



fig 12a

- Data will transfer successfully- a message will be displayed (fig 12b)

- TPMS learn procedure now complete

Firmware for the ATEQ tools is found on the WebVT portal.

You will need to install the WebVT software on a PC or your service lap top. Connect the tools and update them.

WebVT is available for download here:
https://www.ateq-tpms.com/wp-content/uploads/2016/09/WebVT_V8004.zip

If further assistance is required with the update please contact ATEQ customer support department @ 1-888-621-TPMS (8767)



fig 12b

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.