LTB01086NAS3



# TECHNICAL BULLETIN

03 MAY 2018

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

### INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

### Changes are highlighted in blue

### SECTION:

501-14: Handles, Locks, Latches and Entry Systems

### SUBJECT/CONCERN:

Keyless Entry System Lock Function May Not Operate and/or Operates Intermittently

### AFFECTED VEHICLE RANGE:

MODEL: MODEL YEAR: VIN: ASSEMBLY PLANT:	MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
---	--------	-------------	------	-----------------

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery Sport (LC)	2015-2018	501001-734327	Halewood
Discovery (LR)	2017	000127-043056	Solihull
Range Rover Evoque (LV)	2012-2015	600018-999999	Halewood
Range Rover Evoque (LV)	2015-2018	000051-280762	Halewood
Range Rover Sport (LW)	2014-2018	601621-699998	Solihull
Range Rover Sport (LW)	2014-2015	300003-399999	Solihull
Range Rover Sport (LW)	2014-2016	500023-599999	Solihull
Range Rover Sport (LW)	2016-2017	100000-176036	Solihull
Range Rover (LG)	2013-2018	000140-375939	Solihull

## MARKETS:

### **NORTH AMERICA**

## CONDITION SUMMARY:

### SITUATION:

The keyless entry system lock function may not operate or operates intermittently.

### CAUSE:

This may be caused by water ingress into the door exterior handles preventing correct operation of the keyless entry lock function.



### ∧ NOTE:

Certain Steps must be performed by a Jaguar Land Rover-approved bodyshop.

### ACTION:

Should a customer express concern, follow the Workshop Procedure below.

## PARTS:



## △ NOTES:

It is not necessary to replace all door exterior handles; only order the quantity required per the customer concern.

Where door handle covers or inserts are supplied in primer, a maximum allowance of \$32.50 USD or local equivalent has been allocated to cover the cost of paint and materials.

PART NUMBER	DESCRIPTION	QUANTITY
LR061200	Door handle exterior with primed cover (Dimple on handle)	4
LR040667	Door handle exterior with primed cover (Stripes on handle)	4
LR106320	Door handle exterior with primed insert (Dimple - Noble Chrome)	4
LR053502	Door handle exterior with primed insert (Dimple - Bright Chrome)	4
LR068146	Door handle exterior with primed insert (Dimple - Santorini Gloss black)	4
LR096116	Door handle exterior with primed insert (Dimple - Atlas Chrome)	4
LR055917	Door handle exterior - Chrome - Aintree Green	4
LR075119	Door handle exterior - Chrome - Aruba Gold	4
LR055923	Door handle exterior - Chrome - Barolo Black	4
LR055907	Door handle exterior - Chrome - Barossa	4
LR076447	Door handle exterior - Chrome - Carpathian Grey	4
LR055904	Door handle exterior - Chrome - Causeway Grey	4
LR056188	Door handle exterior - Chrome - Corris Grey	4
LR055914	Door handle exterior - Chrome - Firenze Red	4
LR055921	Door handle exterior - Chrome - Fuji White	4
LR055911	Door handle exterior - Chrome - Havana	4

PART NUMBER	DESCRIPTION	QUANTITY
LR055920	Door handle exterior - Chrome - Indus Silver	4
LR055913	Door handle exterior - Chrome - Kaikoura Stone	4
LR046326	Door handle exterior - Chrome - Loire Blue	4
LR055903	Door handle exterior - Chrome - Luxor	4
LR055905	Door handle exterior - Chrome - Mariana Black	4
LR075120	Door handle exterior - Chrome - Montalcino Red	4
LR055906	Door handle exterior - Chrome - Nara Bronze	4
LR055916	Door handle exterior - Chrome - Santorini Black	4
LR067443	Door handle exterior - Chrome - Scotia Grey	4
LR072371	Door handle exterior - Chrome - Yulong White	4
LR013135	Trim panel clip 8.5 x 0.8 - 2.2	38
LR044885	Trim panel clip 8.2 x 1.2 + 2.5 clip	4
LR006101	Trim panel clip 8.2 x 0.7 - 1.5 clip	40
LR090382	Trim panel clip	4
ZZZ001	Paint and materials	\$32.50 USD or local equivalent

# TOOLS:

Refer to Workshop Manual for any required special tools.

## WARRANTY:

## △ NOTES:

It is not necessary to replace all door exterior handles; only order the quantity required per the customer concern.

Certain Steps must be performed by a Jaguar Land Rover-approved bodyshop.

Where door handle covers or inserts are supplied in primer, a maximum allowance of \$32.50 USD or local equivalent has been allocated to cover the cost of paint and materials.

### △ NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Handle - Exterior - Front door - Single - Renew - Discovery Sport (L550)	76.58.07	0.7	49	LR061200
Handle - Exterior - Front door - Pair - Renew - Discovery Sport (L550)	76.58.46	1.4	49	LR061200
Handle - Exterior - Rear door - Single - Renew - Discovery Sport (L550)	76.58.02	0.5	49	LR061200
Handle - Exterior - Rear door - Pair - Renew - Discovery Sport (L550)	76.58.47	1.0	49	LR061200
Handle - Exterior - Front door - Single - Renew - Discovery (L462)	76.58.07	1.1	49	LR061200
Handle - Exterior - Front door - Pair - Renew - Discovery (L462)	76.58.46	2.2	49	LR061200
Handle - Exterior - Rear door - Single - Renew - Discovery (L462)	76.58.02	0.6	49	LR061200
Handle - Exterior - Rear door - Pair - Renew - Discovery (L462)	76.58.47	1.2	49	LR061200
Handle - Exterior - Front door - Single - Renew - Range Rover Evoque (L538)	76.58.07	0.5	49	LR061200
Handle - Exterior - Front door - Pair - Renew - Range Rover Evoque (L538)	76.58.46	1.0	49	LR061200
Handle - Exterior - Rear door - Single - Renew - Range Rover Evoque (L538)	76.58.02	0.4	49	LR061200
Handle - Exterior - Rear door - Pair - Renew - Range Rover Evoque (L538)	76.58.47	0.8	49	LR061200

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Handle - Exterior - Front door - Single - Renew - Range Rover Sport (L494)	76.58.07	0.7	49	LR061200
Handle - Exterior - Front door - Pair - Renew - Range Rover Sport (L494)	76.58.46	1.4	49	LR061200
Handle - Exterior - Rear door - Single - Renew - Range Rover Sport (L494)	76.58.02	0.5	49	LR061200
Handle - Exterior - Rear door - Pair - Renew - Range Rover Sport (L494)	76.58.47	1.0	49	LR061200
Handle - Exterior - Front door - Single - Renew - Range Rover (L405)	76.58.07	0.6	49	LR061200
Handle - Exterior - Front door - Pair - Renew - Range Rover (L405)	76.58.46	1.2	49	LR061200
Handle - Exterior - Rear door - Single - Renew - Range Rover (L405; Standard wheelbase)	76.58.02	0.5	49	LR061200
Handle - Exterior - Rear door - Pair - Renew - Range Rover (L405; Standard wheelbase)	76.58.47	1.0	49	LR061200
Handle - Exterior - Rear door - Single - Renew - Range Rover (L405; Long wheelbase)	76.58.02	0.9	49	LR061200
Handle - Exterior - Rear door - Pair - Renew - Range Rover (L405; Long wheelbase)	76.58.47	1.8	49	LR061200
Door handles - Each/set - Local color	79.E.AJ3	0.6	49	LR061200
Door exterior handle Kit - Single - Assemble	76.58.89.38	0.1	49	LR061200
Door exterior handle Kit - Pair - Assemble	76.58.89.36	0.1	49	LR06120
Door exterior handle Kit - Set of 4 - Assemble	76.58.89.37	0.3	49	LR06120

# △ NOTE:

Normal Warranty procedures apply.




Certain Steps must be performed by a Jaguar Land Rover-approved bodyshop.

ū

# △ NOTE:


Front left door handle shown; others similar.



Identify the existing door exterior handle(s).

- (1) 'dimple' type handle
- **(2)** 'stripe' type handle
- (3) 'chrome' type handle






Record the production date of the NEW door exterior handle(s).

- 1 The label displays the production day and month. ('31/1' = 31 January).
- **2** Peel back the label to display the production year stamp ('17' = 2017).
  - If the production date is 03/08/2017 (03 August 2017) or later, go to Step 4.
  - If the production date is 02/08/2017 (02 August 2017) or earlier, **go to Step 3.**





Inspect the marking(s) on the replacement door exterior handle(s).

- Horizontal marking (1) denotes that the handles are supplied pre-assembled. Go to Step 4.
- Vertical marking (2) denotes that the handles are supplied in kit form. Go to Step 4.
- If the new door exterior handle(s) have neither of the above markings and have a production date of 02/08/2017 or earlier, DO NOT use these parts. Return the parts order new replacement door exterior handles and follow the steps above again.

## ∧ NOTE:

The number of door exterior handles to be replaced will be dependant on the number identified as a concern by the customer.

Identify if the door exterior handles require painting before they are installed.

- If the door exterior handle(s) are supplied in the correct color for the vehicle, go to Step 20.
- If the door exterior handle(s) are supplied in kit form partially in primer (covers or inserts must be painted in the correct color to match the vehicle) go to Step 6.
- If the door exterior handle(s) are supplied pre-assembled partially in primer (covers or inserts must be painted in the correct color to match the vehicle), go to Step 5.

### ① **CAUTIONS:**

DO NOT dismantle pre-assembled door exterior handles before painting as this will cause damage to the weatherproof seals.


This Step must be performed by a Jaguar Land Rover-approved bodyshop.

Labor time is included in the SRO make sure care is taken when masking the door handle for painting. Accurate masking is essential to achieve a satisfactory finish on the exterior door handle.



### ∧ NOTE:

This step is only applicable to pre-assembled door exterior handles that require painting.




## **Masking directions:**

- Type (1) handles: mask the areas highlighted in blue. Part numbers: LR040667, LR061200.
- Type (2) handles: mask the areas highlighted in blue. Part numbers: LR0106320, LR053502, LR068146, LR096116.
- Paint the door exterior handle covers/inserts in the correct color to match the vehicle.
  - For pre-assembled door exterior handles, allow the paint to dry.
    - Once the paint is dry, remove the tape and go to Step 20.
  - For door exterior handles in kit form, allow the paint to dry.
    - Once the paint is dry, **go to Step 7**.

7

## △ NOTE:


Only applicable to door exterior handles with painted inserts.



Install the painted door exterior handle insert into the door exterior handle cover (1).

- The painted door exterior handle insert is shown in the installed position (2).
- Viewed from the rear, make sure all the clips are engaged (3) and that the door exterior handle insert is securely installed.






Prepare the door exterior handle strap inner and electronic module for assembly.

• Remove the yellow backing from the tape on the electronic unit.





Insert the electrical connector through the door exterior handle strap inner.

## △ NOTE:

Make sure the electrical connector is correctly orientated ( $\checkmark$ ).



Clip the electrical connector into the handle strap inner ( $\checkmark$ ).




Install the antenna and electronic unit into the handle strap inner; align the clip with the handle strap inner rib.

■ Firmly press the electronic unit onto the handle strap inner; make sure the self adhesive tape makes good contact.






Remove and discard the white tape from the electronic unit.



Assemble the inner and outer sections of the door exterior handle by clipping the 2 sections together.

- Hook the outer door handle cover around the end of the inner door handle strap
  (1).
- Rotate the outer door handle cover about point (1) and clip the inner door handle strap into the outer door handle cover (2).
- Firmly squeeze the door handle strap assembly at the electronic module end to make sure the self adhesive tape makes good contact with the handle strap inner and the handle cover.






Install the 2 screws into the handle strap.





Start the installation of the door exterior handle gasket.






Make sure the wiring harness is positioned.

# △ NOTE:

Make sure the gasket lies flat when it has been installed.



Install the rubber gasket onto the door exterior handle strap.

- Make sure the rubber gasket is installed over the 2 locating pins on the handle base.
- Make sure the rubber gasket is installed over the 4 locating pins, 2 either side of the wiring harness.





Make sure the rubber gasket sits flush against the handle base and the locating lug at the front of the gasket is installed into the hole in the handle  $(\checkmark)$ .

Repeat steps 7-18 for any remaining handles that require replacement.

20

## ∧ NOTE:

Only complete this step if 1 or more front door exterior handles have been identified as part of the customer's concern.

Replace the defective front door exterior handle(s) (see TOPIx Workshop Manual section 501-14: Handles, Locks, Latches and Entry Systems - Exterior Front Door Handle).

21

### ∧ NOTE:

Only complete this step if 1 or more rear door exterior handles have been identified as part of the customer's concern.

Replace the defective rear door exterior handle(s), (see TOPIx Workshop Manual section 501-14: Handles, Locks, Latches and Entry Systems - Exterior Rear Door Handle).