

**On-car analysis list from April 5th, 2021**  
**please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Atlas, Atlas Cross Sport	20-21	3.6L (CDVC)	All	MIL-on P0087 P0148 P053F	Customer states MIL-on <b>(Must have P0087, P0148 and/or P053F fault codes)</b> <b>(Untouched vehicles)</b>
<b>Chassis</b>	Jetta	20-21	All	All	Front End Noise	Customer states front suspension noise while driving <b>(possibly while turning or going over bumps)</b> <b>(Untouched vehicles)</b>
<b>Body</b>	Tiguan	19-21	All	All	Rear Tailgate Strut Broken/Loose/Detached	Customer states rear tailgate strut broken/loose/detached