



TECHNICAL SERVICE BULLETIN

Classification: KS17-042C	Reference: NTB17-127C	Date: May 20, 2024
------------------------------	--------------------------	-----------------------

INTELLIGENT KEY INITIALIZATION PROCEDURE STOPS OR WILL NOT CONTINUE

This bulletin has been amended. See **AMENDMENT HISTORY** on the last page.
Discard all previous versions of this bulletin.

APPLIED VEHICLES: 2017-2018 Altima (L33)
2020-2024 Frontier (D40/D41)
2017-2023 Maxima (A36)
2017-2024 Murano (Z52)
2017-2020 Pathfinder (R52)
2017-2024 Titan/Titan XD (A61)
2023-2024 Z (Z34)

SERVICE INFORMATION

When the initialization procedure being performed with a new or existing Intelligent Key is interrupted (the procedure stops or will not continue), the BCM may be left in learn mode and will not function until it returns to normal mode. Under this condition, the BCM and Intelligent Key(s) will not function normally. If this condition occurs, the BCM must be returned to normal mode and the initialization procedure started over.

To get back to the beginning of the initialization procedure, use one of the following procedures:

- Successfully perform the initialization procedure using one of the original Intelligent Keys twice consecutively.
 - Each successful initialization will follow with two (2) quick tones.

OR

- When the initialization procedure cannot be successfully performed twice (more than two quick tones), perform the initialization procedure five (5) times using the inoperative "failed" Intelligent Key.
 - Initialization does not need to be successful when performed five (5) times.

When returning to normal operating mode, the initialization procedure for all Intelligent Keys may be started again.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 18, 2017	NTB17-127	Original bulletin published
March 17, 2021	NTB17-127A	Classification Number updated
February 22, 2022	NTB17-127B	Updated APPLIED VEHICLES
May 20, 2024	NTB17-127C	Updated APPLIED VEHICLES

