



Service Bulletin


Bulletin No.: 24-NA-043

Date: August, 2024

INFORMATION

Subject: Information on Fuel Injector Flow Rate Number on the Fuel Injector has too Many Characters

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2020	2024			LM2	
Chevrolet	Silverado 1500	2020	2021			LM2	
	Silverado 1500 - LTD (RPO J21, VIN Digit 5 = W/Y)	2022	2022				
	Silverado 1500 - New (RPO J22, VIN Digit 5 = A/D)						
	Silverado 1500	2023	2025			LZ0	
	Suburban	2021	2025			LM2	
	Tahoe						
GMC	Sierra 1500	2020	2021			LM2	
	Sierra 1500 - Limited (RPO J21, VIN Digit 5 = 8/9)	2022	2022				
	Sierra 1500 - New (RPO J22, VIN Digit 5 = H/U)						
	Sierra 1500	2023	2025			LZ0	
	Yukon Models	2021	2025			LM2	

<p>Involved Region or Country</p>	<p>North America, Europe, Kazakhstan, Uzbekistan, Russia, Middle East, Israel, Palestine, Argentina (Mercosur), Brazil (Mercosur), Bolivia (West), Chile (West), Colombia (West), Ecuador (West), Paraguay (West), Peru (West), Uruguay (West), Japan, Cadillac Korea (South Korea), Philippines, Australia/New Zealand, Other Africa</p>
<p>Information</p>	<p>Some technicians may find that the fuel Injector Flow Rate number on the fuel injector has too many characters.</p>  <p>Omit these "00" when programming the fuel injector.</p> <p style="text-align: right;">6567963</p>

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

<p>Version</p>	<p>2</p>
<p>Modified</p>	<p>Released March 07, 2024 Revised August 09, 2024 - Added 2025 to Model Year.</p>

Key words: **P026D**, P0201, P0202, P0203, P0204, P0205, P0206, P0261, P0262, P0264, P0265, P0267, P0268, P0270, P0271, P0273, P0274, P0276, P0277, P1248, P1249, P124A, P124B, P124C, P124D, P2147, P2148, P2150, P2151, P2153, P2154, P020A, P020B, P020C, P020D, P020E, P020F, P02CC, P02CD, P02CE, P02CF, P02D0, P02D1, P02D2, P02D3, P02D4, P02D5, P02D6, P02D7, P02EE, P02EF, P02F0, P02F1, P02F2, P02F3, P0300, P0301, P0302, P0303, P0304, P0305, P0306, P268C, P268D, P268E, P268F, P2690, P2691, **misfire, rough, IQA, injector flow rate programming.**

