

Technical Service Bulletin

Topic	45 Gear cannot be selected in cold weather (DTCs: U303500; U029400; U012900)
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2077740/1
Level	EH
Status	Released for publishing
Release date	Apr 18, 2025

New customer code

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> malfunction display symbols -> parking brake malfunction display	functionality -> does not activate	
transmission -> transmission control operation -> gear/driving position change	functionality -> no function	
transmission -> transmission control operation -> gear/driving position change	functionality -> partially out of order	
transmission -> transmission control operation -> gear/driving position change	functionality -> operation sequence incorrect	
transmission -> transmission control operation -> shift lever lock	functionality -> no function	
transmission -> transmission control operation -> shift lever lock	functionality -> partially out of order	
transmission -> transmission control operation -> driving program change	functionality -> no function	
transmission -> transmission control operation -> driving program change	functionality -> operation sequence incorrect	
transmission -> transmission control operation -> engage gear/driving position	functionality -> no function	
transmission -> transmission control operation -> engage gear/driving position	functionality -> partially out of order	
transmission -> transmission control operation -> engage gear/driving position	functionality -> operation sequence incorrect	
transmission -> transmission control operation -> engage gear/driving position	functionality -> cannot be selected	
chassis -> brakes, brake regulation -> electronic parking brake (EPB)	functionality -> no function	
chassis -> brakes, brake regulation -> electronic parking brake (EPB)	functionality -> cannot be switched on/activated	
chassis -> brakes, brake regulation -> electronic parking brake (EPB)	functionality -> cannot be switched off/deactivated	
chassis -> brakes, brake regulation -> anti-lock braking system (ABS)	functionality -> no function	
chassis -> brakes, brake regulation -> electronic stabilization control (ESC)	functionality -> no function	

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> indicator display symbols -> parking brake indicator display	functionality -> activates	
information, navigation, communication, entertainment -> indicator display symbols -> driving dynamics regulation (ESC) indicator display	functionality -> activates	
information, navigation, communication, entertainment -> malfunction display symbols -> ABS malfunction display	functionality -> activates	
information, navigation, communication, entertainment -> malfunction display symbols -> parking brake malfunction display	functionality -> activates	
information, navigation, communication, entertainment -> warning display symbols -> parking brake warning display	functionality -> activates	
information, navigation, communication, entertainment -> warning display symbols -> brake failure warning display	functionality -> activates	

Vehicle data

Q6

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
GF*	2025	A		*	*	*

Documents

Document name
master.xml



Connection offline

Technical Service Bulletin

Transaction No.: **2077740/1**

45 Gear cannot be selected in cold weather (DTCs: U303500; U029400; U012900)

Release date: Apr 18, 2025

Condition

Customer states:

Sometimes gears cannot be selected during cold weather. This may occur together with a fault message for the parking brake.

Workshop findings:

The complaint can be reproduced; however, a change occurs after an extended period in warmer surroundings.

The following combination of DTCs occur together and simultaneously.

Address 0003:

- **U303500** with Symptom code 678
- **U029400** with Symptom code 48

Address 812C:

- **U303500** with Symptom code 289
- **U012900** with Symptom code 38248
- **U012900** with Symptom code 38255

Technical Background

Control unit information is not communicated at the right time.

Production Solution

Not applicable

Service

If the complaint applies completely, please replace **the brake servo control unit as an individual part** and send it in for analysis.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4545		
Damage Code:	0040		
Labor Operations:	Replace ABS and electronic differential lock control unit	4545 55xx	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol

Claim Comment:	As per TSB 2077740/1
-----------------------	----------------------

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Required Parts and Tools

Please only replace the control unit as an individual part and not the entire brake servo.

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Control unit for brake servo	01

Additional Information

All part and service references provided in this TSB (**2077740**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.