

### **Delivery STOP340011 for the S 1000 R and M 1000 R, and S 1000 XR models**

A delivery stop has been announced for the M 1000 R (KM3), S 1000 R (K63), and S 1000 XR (K69) produced between 9-25-2025 and 11-25-2025. Fewer than 100 units are affected overall with **only 2 units in dealer inventory** at this time.

During a quality inspection it was discovered that some front brake lines may have corrosion.

Consequently, the brake function may be impacted.

Potentially affected vehicles are flagged in AIR (Aftersales Information Research) with campaign code STOP340011. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

If you have a vehicle in your new/used inventory matching the above description it cannot be retailed at this time.

The Analysis is still taking place, and no vehicles should be impromptu repaired until it is determined if any technical measures are required.

Nov 26, 2025