

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

04-JUN-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

723544

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1GCDG14Z3NZ214801	CHEVROLET TRU	C1500	1992	

Purchase Date 01-MAY-1992	Dealer's Name _____	Engine Size (CID/CC/L) <u>4.3 LI</u>	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☒ Pick Up Truck ☐ Other _____
--	---	--	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 03270000 03242000 07464000	Part Name(s) BRAKES:HYDRAULIC:SHOE:DISC BRAKE SYSTEM BRAKES:HYDRAULIC:LINES:HOSE:NON-METALLIC POWER TRAIN:AXLE ASSEMBLY:SEAL:AXLE SHAFT	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 1	Date(s) of Failure(s) <u>28-MAY-2000</u> Mileage at Failure(s) <u>40000</u> Vehicle Speed at Failure(s) <u>45</u>	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

REPAIR SHOP REPORTS AN OBSTRUCTION IN THE HYDRAULIC SYSTEM OF TRUCK'S FRONT BRAKES, REQUIRING REPLACEMENT OF FRONT BRAKE HOSES, LINES, CALIPERS AND BRAKE PADS. ALSO, THERE IS A FAILURE OF THE REAR AXLE SEALS OF THE TRUCK, CAUSING DAMAGE TO THE REAR BRAKES. THE SHOP, SULLIVAN'S AUTOMOTIVE SERVICE OF KINGWOOD, TX, ALSO TOLD ME THEY HAVE REPEATEDLY OBSERVED FAILURE OF '91-'95 GM TRUCK REAR AXLE SEALS, WHICH AFFECTS THE PERFORMANCE OF THE TRUCK'S BRAKING SYSTEM. THE COST TO REPAIR THIS DEFECT IN MY VEHICLE IS APPROXIMATELY \$1300. *AK

CONTINUED ON BACK (SEE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.