

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

258

Date Received

14-SEP-2000

Od_or

rt_dt

od_rt

up_ltr

Reference No.

731375

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located at front of vehicle or on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
	SPARTAN	CHARGER	1994	

Purchase Date 01-JAN-1994	Dealer's Name _____	Engine Size (CID/CCL) 552 CI	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other	Body Style ☐ Sport Vlt ☐ Truck ☐ Motorcycle ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other
--	---	--	--	---	--	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06310000	Part Name(s) ELECTRICAL SYSTEM;WIRING;HARNES;FRONT;UNDERHOOD	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures 2	Date(s) of Failure(s) 01-SEP-2000 Mileage at Failure(s) 70000 Vehicle Speed at Failure(s) 2	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☒ Yes ☐ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE SFD HAS SIX FIRE APPARATUS WITH THIS CHASSIS FROM THE 93 AND 94 MODEL YEARS. TWO HAVE HAD ELECTRICAL FAILURES IN THE WIRING HARNES BETWEEN THE LEFT BATTERY BANK AND THE STARTER. I PERSONALLY WAS DRIVING ONE OF THEM WHEN TOTAL ELECTRICAL FAILURE SHUT OFF ALL POWER INCLUDING LIGHTS (ENGINE 20). ENGINE 10 CAUGHT FIRE IN THE FIRE STATION APPARATUS BAY AND WAS DISCOVERED BEFORE SERIOUS STRUCTURAL DAMAGE TO THE FIRE STATION OCCURRED. THE SPECIFICS AS TO MILEAGE AND DATE ARE APPROXIMATE. I AM REPORTING THIS ON MY OWN NOT AS AN OFFICIAL DEPARTMENT REPRESENTATIVE. THE ADDRESS AND PHONE NUMBER PROVIDED ARE MY HOME.

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.