

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

258

Date Received

14-SEP-2000

Od_or

rt_dt

od_rt

up_ltr

Reference No.

731433

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FMCU22X4RUB80026	FIRESTONE	WILDERNESS	1900	

Purchase Date

01-OCT-1998

Dealer's Name

Engine Size

(CID/CCL)

☐ Turbo☐ Diesel☐ Gas☐ Fuel Injection☐ New ☒ Used

City _____ State _____ Zip Code _____

No. Cylinders

Transmission Type

☐ Manual☐ Automatic

Antilock Brakes

☐ Yes☒ No

Restraint System

☐ 3-Point Belt☐ Driverside Airbag☐ Passengerside Airbag☐ Motorbelt☐ 2-Point Belt

Cruise Control

☐ Yes☒ No

Drive Train

☒ Front☐ Rear☐ 4-Wheel

Vehicle Type

☐ Car☐ Van☐ Minivan☐ Other☐ Sport Vlt☐ Truck☐ Motorcycle

Body Style

☐ 2-Door☐ 4-Door☐ Stationwagon☐ Pick Up Truck☒ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02740000	Part Name(s) TIRES: TREAD	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures 1	Date(s) of Failure(s) 2E-NOV-1999 Mileage at Failure(s) 90560 Vehicle Speed at Failure(s)	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 2	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☒ Yes ☐ No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

TRAVELING WITH BOAT IN TOW, WHEN THE LEFT REAR TIRE SUFFERED A TREAD SEPARATION, CAUSING THE VEHICLE TO ROLL OVER, RESULTING IN THE FORD EXPLORER AND THE BOAT BOTH BEING TOTALED. BOTH OCCUPANTS OF THE VEHICLE WERE INJURED.*AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

258

Date Received

14-SEP-2000

Od_or

rt_dt

od_rt

up_ltr

Reference No.

731433

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located between of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FMCU22X4RUB80026	FORD TRUCK	EXPLORER	1994	

Purchase Date 01-OCT-1998	Dealer's Name _____	Engine Size (CID/CCL) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Driver's Side Airbag ☐ Passenger's Side Airbag ☐ Motorized ☐ 2-Point Belt	Cruise Control ☐ Yes ☒ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other ☐ Sport Utl ☐ Truck ☐ Motorcycle	Body Style ☐ 2-Door ☐ 4-Door ☐ Station Wagon ☐ Pick Up Truck ☒ Other
--	---	---	--	---	---	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02740000	Part Name(s) TIRES: TREAD	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures 1	Date(s) of Failure(s) 2E-NOV-1999 Mileage at Failure(s) 90560 Vehicle Speed at Failure(s) _____	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 2	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☒ Yes ☐ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

TRAVELING WITH BOAT IN TOW, WHEN THE LEFT REAR TIRE SUFFERED A TREAD SEPARATION, CAUSING THE VEHICLE TO ROLL OVER, RESULTING IN THE FORD EXPLORER AND THE BOAT BOTH BEING TOTALED. BOTH OCCUPANTS OF THE VEHICLE WERE INJURED.*AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.