

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

258

Date Received

20-SEP-2000

Od_or

rt_dt

od_rt

up_ltr

Reference No.

732041

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located at front of vehicle left of driver's seat)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1J4FY49S0XP469728	JEEP	WRANGLER	1999	

Purchase Date 01-APR-1999	Dealer's Name _____	Engine Size (CID/CCL) 4.0L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other	Body Style ☐ Sport Vlt ☐ Truck ☐ Motorcycle ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other
--	---	--	--	---	--	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 12110000 09530000	Part Name(s) INTERIOR SYSTEMS: PASSIVE RESTRAINT: AIR BAG COMMUNICATIONS: HORN ASSEMBLY: HORN	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures 3	Dates of Failure(s) 01-OCT-1999 Mileage at Failure(s) 4000 Vehicle Speed at Failure(s) 2	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

IF INTERIOR OF VEHICLE BECOMES DAMP - EITHER THROUGH RAIN WITH TOP INADVERTANTLY LEFT DOWN, OR BY CLEANING AS INDICATED (WITH HOSE) IN OWNER'S VIDEO TAPE AND INFORMATION - THE CLOCK SPRING SHORTS OUT CAUSING 1) AIR BAG SYSTEM FAILURE 2) HORN TO GO OFF CONSTANTLY 3) INTERMITTENT DRIVABILITY CONCERNS. DEALERSHIP CONTINUALLY REPLACES RUSTY CLOCK SPRING - HOWEVER HAS NO RESOLUTION FOR SITUATION CAUSE BY NORMAL USE AS INDICATED IN OWNER'S INFORMATION (AND ALL OTHER PREVIOUSLY OWNED JEEP WRANGLERS). *AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.