



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

24-FEB-2001

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

741429

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1G1NE52J4Y6181437	CHEVROLET	MALIBU	2000	

Purchase Date 01-APR-2000	Dealer's Name _____	Engine Size (CID/CC/L <u>3100 S</u>)	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 03250000	Part Name(s) BRAKES:HYDRAULIC:ANTI-SKID SYSTEM	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) <u>19-JAN-2001</u> Mileage at Failure(s) <u>6500</u> Mileage at Failure(s) <u>50</u>	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

AT 6,499 MILES ODOMETER READING, THE DEALER ROTATED TIRES. AT THAT POINT THE CAR FRONT VIBRATED, STEERING WHEEL SHAKES, AND BRAKES PULSATE WHEN BRAKES ARE APPLIED. THERE WERE NO PROBLEMS PRIOR TO THE DEALER ROTATING THE TIRES WHEELS; SERVICE REP INDICATED MOST LIKELY ROTORS WERE DAMAGED WITH AIR TORQUE TIGHTENED LUGS TOO TIGHT; DAMAGED ROTORS. SPRINGS IN REAR CONTINUE TO SQUEAK. FACTORY DEFAULTS? BULLETINS? HOW TO OBTAIN?

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.