



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

14-MAY-2001

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

745311

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side door) WVWMA63B1WE242094	Vehicle Make VOLKSWAGEN	Vehicle Model PASSAT	Vehicle Year 1998	Current Odometer Reading
Purchase Date 01-FEB-1998	Dealer's Name _____		Engine Size (CID/CC/L ?)	☒ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06850000 05230000 05151000	Part Name(s) EXHAUST SYSTEM:CATALYTIC CONVERTER SYSTEM ENGINE COOLING SYSTEM:PUMP:WATER ENGINE:TIMING GEAR AND CHAIN	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 01-JAN-2001 Mileage at Failure(s) _____	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

CATALYTIC CONVERTER REPLACED EARLY ON IN OWNERSHIP. WATER PUMP, OIL PUMP, TIMING BELT REPLACED TWO MONTHS AGO. TURBO REPLACED TWICE AND STILL DEFECTIVE. ELECTRICAL PROBLEMS WITH DRIVER'S SIDE WINDOW, HEATED SEAT, TRUNK LIGHT. SUSPENSION SYSTEM BUSHINGS NEED REPLACEMENT @ ONLY 56,000 MILES. STEERING COLUMN REPLACED EARLY ON.

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.