



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

16-NOV-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

754615

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side door) 1J4FF68S1XL512354	Vehicle Make JEEP	Vehicle Model CHEROKEE	Vehicle Year 1999	Current Odometer Reading
Purchase Date 01-NOV-1998	Dealer's Name _____		Engine Size (CID/CC/L) 4 L	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☒ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 07150000 07200000	Part Name(s) POWER TRAIN:CLUTCH ASSEMBLY:LEVEL:RELEASE:THROW:OL POWER TRAIN:TRANSMISSION:STANDARD:MANUAL	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part's ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 12-NOV-2001 Mileage at Failure(s) 55000 Vehicle Speed at Failure(s) 15	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE DEALER SAID THEY HAVE SEEN THIS PROBLEM IN MANY WRANGLERS WITH THE SAME CLUTCH AND TRANSMISSION. THE THROW-OUT BEARING HAS ROTATED ON THE CLUTCH FORK AND THE FORK HAS BEEN PUSHED DOWN OVER THE THROW-OUT BEARING, CAUSING THE CLUTCH SLAVE TO EXTEND TO THE MAXIMUM, WHICH CAUSES THE CLUTCH NOT TO BE ABLE TO BE DEPRESSED. THEREFORE, I WAS DRIVING DOWN THE STREET WITH A NON-OPERATIONAL VEHICLE. THIS WAS A DANGEROUS SITUATION.

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.