



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY §20

Date Received

14-JAN-2002

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

8002081

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side)		Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1GKDT13W4T2570935		GMC	JIMMY	1996	
Purchase Date	Dealer's Name		Engine Size (CID/CC/L)	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection	
☐ New ☒ Used	City _____ State _____ Zip Code _____		No Cylinders _____		
Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type
☐ Manual ☐ Automatic	☒ Yes ☐ No	☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag	☒ Yes ☐ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other
		☐ Motorbelt ☐ 2-Point Bel		☐ Sport Utl ☐ Truck ☐ Motorcycle	☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 10312000	Part Name(s) VISUAL SYSTEMS:WINDSHIELD WIPER:MOTOR	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Dates of Failure(s) 25-NOV-2001	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 83877		
	Vehicle Speed at Failure(s)		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☐ No	Number of Persons Injured C	Number of Fatalities 0	Estimated Property Damag	Reported to Police ☐ Yes ☐ No
---	--	--------------------------------	---------------------------	--------------------------	--

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WINDSHIELD WIPERS OPERATE INTERMITTENTLY DURING INCLEMENT WEATHER. DEALERSHIP EXAMINED VEHICLE AND DETERMINED SOLDER JOINTS NEAR WIRING HARNESS CONNECTOR IS CRACKED. THE VEHICLE IS NOT INCLUDED IN RECALL CAMPAIGN 98V150001 DUE TO VIN. PLEASE PROVIDE ANY ADDITIONAL INFORMATION / DOCUMENTATION.*AK

COPIES OF REPORTS - FREE -

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.