



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 252

Date Received

06-FEB-2002

Od_or

rt_dt

od_rt

ip_lr

Reference No.

8003678

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side)		Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1MELM50UXSA615524		MERCURY	SABLE	1995	
Purchase Date	Dealer's Name _____		Engine Size (CID/CC/L _____)	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection	
☐ New ☒ Used	City _____ State _____ Zip Code _____		No Cylinders _____		
Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type
☐ Manual ☐ Automatic	☐ Yes ☐ No	☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	☐ Yes ☐ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other _____
					☐ Sport Utl ☐ Truck ☐ Motorcycle ☐ Body Style
					☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 11100000	Part Name(s) HEATER:WATER:DEFROSTER:DEFOGGER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Dates of Failure(s) 01-JAN-2002	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 84800		
	Vehicle Speed at Failure(s)		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☐ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☐ No
---	--	---------------------------	----------------------	--------------------------	--

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

REAR DEFOGGER INSIDE OF VEHICLE DOESN'T PRODUCE ENOUGH HEAT TO DEFOG WINDOW LOCATED IN BACK. DEALERSHIP IS AWARE OF PROBLEM.*AK

COPIES OF REPORTS ARE KEPT

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.