



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 241

Date Received

30-APR-2002

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

8008839

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side)		Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
5BCA01612WF061375		GEORGIE BOY	CRUISE MASTER	1998	
Purchase Date	Dealer's Name _____		Engine Size (CID/CC/L _____)	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection	
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____		
Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type
☐ Manual ☐ Automatic	☐ Yes ☒ No	☒ 3-Point Belt ☒ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Bel	☐ Yes ☐ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other _____ ☐ Sport Utl ☐ Truck ☐ Motorcycle
				Body Style	
				☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____	

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06012020	Part Name(s) FUEL: LPG LINES: NON-METALLIC	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part's ☐ Original ☐ Replacement
No of Failure	Dates of Failure(s) 01-APR-2002	Failed Part(s)	NHTSA Previously
	Mileage at Failure(s) 17000	☐ Yes ☐ No	☐ Yes ☐ No
	Vehicle Speed at Failure(s)		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash	Fire	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police
☐ Yes ☐ No	☐ Yes ☐ No				☐ Yes ☐ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

98 V 310 000/GAS LINE: PROPANE GAS LINE IS CRIMPED BY THE ARM ATTACHED TO IT. *AK

COPIES OF REPORTS ARE KEPT

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.