

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

156

Date Received

29-AUG-2000

Od_or

rt_dt

od_rt

up_ltr

Reference No.

869044

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
JH2SC4407YM001966	HONDA MOTORCYCLE	CBR900	2000	

Purchase Date	Dealer's Name	Engine Size (CID/CC/L)	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City	No. Cylinders	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Driver's Side Airbag ☐ Passenger's Side Airbag ☐ Motorcyclist ☐ 2-Point Belt	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other	Body Style ☐ Sport Vlt ☐ Truck ☐ Motorcycle ☐ 2-Door ☐ 4-Door ☐ Station Wagon ☐ Pick Up Truck ☐ Other
--	---	--	--	--	--	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05100000	Part Name(s) ENGINE	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures	Date(s) of Failure(s) 01-MAY-2000 Mileage at Failure(s) 1 Vehicle Speed at Failure(s)	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE DRIVING 45 + THE FRONT END SHAKE AND VIBRATES VERY HARD WHICH MAY CAUSE A LOSS OF VEHICLE CONTROL. DLR SAID ITS THE CHARACTERISTICS OF THE MOTORCYCLE. PLEASE PROVIDE FURTHER INFORMATION.

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.