

## Quality Monitoring Report



<b>QMR Id</b> QMR1- [REDACTED]	<b>Created By</b> apor	<b>Report Date</b> 04/23/2019	<b>Last Updated</b> 04/23/2019	<b>Reg-Zn-Dst</b> [REDACTED]	<b>Dealer</b> 090491
<b>Section</b> Electrical	<b>Sub Section</b> SRS Airbag & Pretentioners				
<b>VIN</b> JF2SJAWC1H [REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 20655		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 04/18/2019	<b>Failed Part #</b> --	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
<b>Property Damage</b> N					
<b>DTC Code(s)</b> B1650					

<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> --
------------------------------------	-------------------------------------	------------------------------------

### Customer's Description of Complaint

SRS light

### Technician's Findings and Repair

Tech code B1650 , tech will replace pass seat bottom, vehicle not withing date of manufacture for collection. Vehicle to be repaired and returned to customer. Reviewed by phone with FSE

### Attachments

No Attachments Found

<b>VIN Remainder</b> JF2SJAWC1HH [REDACTED]	<b>Warranty Start Date</b> 05/31/2017	<b>Production Date</b> 04/14/2017	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2017	<b>Model Code</b> HFJ
<b>Color</b> SBM	<b>Options</b> 34	<b>Emission Spec</b> C	<b>Turbo</b> N
<b>Engine Size</b> 2.5	<b>Original Trans #</b> [REDACTED]		

