



Utilimaster Corporation
65906 State Road 19,
P.O. Box 585
Wakarusa, IN 46573

DEFECT AND NONCOMPLIANCE REPORT - DOMESTIC

Description:	"PRNDL" Cable may break at the attachment to the transmission control selector arm assembly mounted on the steering column
---------------------	--

Internal Code:	N/A	Date of Report:	2/27/2012
-----------------------	-----	------------------------	-----------

Submitted to: Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Ave. SE
Washington, DC 20590

Attn: Mrs. Kelly Schuler, Office of Defects Investigation
Fax: (202) 366-7882
Email: RMD.ODI@dot.gov

Manufacturer Identification: Utilimaster Corporation
65906 State Road 19
P.O. Box 585
Wakarusa, IN 46573

Corporate contact for recall information:

Wesley D. Chestnut
Compliance and Validation
Spartan Motors, Inc.
(517) 543-6400, ext. 3275
Fax: (517) 543-7729
Email: wdchestn@spartanmotors.com

Preparer's Signature:

III. DESCRIBE THE DEFECT OR NONCOMPLIANCE

Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.

The "PRNDL" cable may break at the attachment to the transmission control selector arm assembly mounted on the steering column. If the indicator cable breaks, the transmission gear indication in the "PRNDL" display in the instrument cluster remains in the "1" position (first gear) regardless of gear selected.

Describe the cause(s) of the defect or noncompliance condition.

Utilimaster has not been made aware of the cause.

Describe the consequence(s) of the defect or noncompliance condition.

An incorrect gear indication in the instrument panel may prevent the driver from knowing if they are in park or reverse, increasing the risk of a crash.

Identify any warning which can (a) precede or (b) occur.

This may occur without warning

If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address:

Generic Component Name:	N/A
Supplier Part Number:	N/A
Utilimaster Part Number:	N/A
Supplier Corporate Name:	N/A
Address:	N/A
CEO or Knowledgeable Rep:	N/A

IV. PROVIDE THE CHRONOLOGY IN DETERMINING THE DEFECT/NONCOMPLIANCE

If defect, furnish a chronological summary with dates of all the principle events that were the basis for the determination of the defect. Include number of reports, accidents, injuries, fatalities, and warranty claims.

17FEB12 - Utilimaster receives notice from Ford.

23FEB12 - Utilimaster determines the population.

27FEB12 - Utilimaster notifies NHTSA for U.S. and Transport Canada for Canada.

If noncompliance, identify and provide the test results or other data in chronological order with dates on which the noncompliance was determined.

N/A

V. IDENTIFY THE REMEDY

Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

Refer to Ford Motor Company recall 12V-035.

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

Refer to Ford Motor Company recall 12V-035.

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

On October 26, 2011 transmission shift lever stock at the Ford assembly plant was replaced with properly manufactured stock that did not have a sharp edge in the area where the "PRNDL" indicator cable attaches.

VI. IDENTIFY THE RECALL SCHEDULE

Furnish a schedule or agenda, with specific dates, for notification to other manufacturers, dealers/retailers, and purchasers. Please identify any foreseeable problems with implementing this recall.

Refer to Ford Motor Company recall 12V-035.

VII. FURNISH RECALL COMMUNICATIONS

Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification.

DOCUMENT DESCRIPTION	DATE AND MANNER SUBMITTED
Notification letter to other manufacturers	N/A
Draft Notification letter to purchasers	2-Mar-12
Press release (if applicable)	N/A
Recall Service Bulletin (RSB)	Refer to 12V-035
Notification Envelope	Pre-approved

The manufacturer's campaign identification number if not identical to the number assigned by

N/A