



Ford Motor Company  
Customer Service Division  
PO Box 1904  
Dearborn, Michigan 48121



771500467036

A/1/000003/1



January 2026

JOHN A. SAMPLE  
123 SAMPLE ST  
SAMPLE CITY, MI 12345-6789

**\*\*\* IMPORTANT SAFETY RECALL \*\*\***

**Safety Recall Notice 25SD6 / NHTSA Recall 25V829**

2020 Escape

This Notice Applies to Your Vehicle, Vehicle Identification Number (VIN): [REDACTED]

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2020-2022 and 2025 model year Escape vehicles equipped with a panoramic sunroof, including the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

**What is the issue?** On your vehicle, the liftgate hinge covers may become partially or fully detached. You may notice the covers are not fully seated or hear wind noise and rattling noise as you drive prior to detachment.

**What is the risk?** A hinge cover that detaches while driving can create a road hazard for other road users, increasing the risk of a crash.

**What will Ford and your dealer do?** **Parts are not available.** Ford Motor Company is working to provide parts for this repair. When the remedy becomes available, Ford Motor Company will notify you via mail to schedule a service appointment with your dealer for repairs to be completed free of charge.

**What should you do?** Ford has not issued instructions to stop driving your vehicle under this safety recall. When the remedy is available, you should contact your dealer for an appointment to have your vehicle remedied as soon as practicable. If you do not already have a servicing dealer, you can access [ford.com/support](https://ford.com/support) for dealer addresses, maps, and driving instructions.

**What should you do?  
(continued)**

If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-888-275-9171) or go to [NHTSA.gov](https://www.nhtsa.gov). Reference NHTSA Safety Recall 25V829.

**Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.**

NOTE: You can receive information about Recalls and Customer Satisfaction Programs through our Ford App. The app can be downloaded through the App Store or Google Play. In addition, there are other features, such as reserving parking in certain locations and controlling certain functions on your vehicle (lock or unlock doors, remote start) if it is equipped to allow control.

**What if you no longer own this vehicle?**

If you no longer own this vehicle and have an address for the current owner, please forward this letter to the new owner.

You received this notice because government regulations require that notification be sent to the last known owner of record. Our records are based primarily on state registration and title data, which indicate that you are the current owner or lessee.

Thank you for your attention to this important matter.

Customer Service Division



Ford Motor Company  
División de Servicio al Cliente  
PO Box 1904  
Dearborn, Michigan 48121



771500467036

A/3/000003/1



Enero de 2026

JOHN A. SAMPLE  
123 SAMPLE ST  
SAMPLE CITY, MI 12345-6789

## **\*\*\* CAMPAÑA DE SEGURIDAD IMPORTANTE \*\*\***

### **Aviso de Campaña de seguridad 25SD6 / Campaña 25V829 de la NHTSA**

2020 Escape

Este aviso se relaciona con su vehículo con el número de identificación del vehículo (VIN):



Este aviso se le envía de acuerdo con la Ley Nacional de Seguridad de Tránsito y Vehículos Motorizados de los EE. UU.

Ford Motor Company ha determinado que existe un defecto relacionado con la seguridad del vehículo en algunos Escape año modelo 2020-2022 y 2025, equipados con techo corredizo panorámico, incluido el suyo, con el VIN que aparece arriba.

Lamentamos esta situación y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su concesionario, es ofrecerle servicio y apoyo de alto nivel.

#### **¿Cuál es el problema?**

En su vehículo, las cubiertas de las bisagras de la compuerta levadiza podrían desprenderse parcial o totalmente. Es posible que observe que no están completamente asentadas o que escuche ruidos de viento y traqueteo al conducir, antes de que se desprendan.

#### **¿Qué riesgo existe?**

Una cubierta de bisagra que se desprende mientras se conduce puede crear un peligro para otros usuarios de la carretera, lo que aumenta el riesgo de choque.

#### **¿Qué medidas adoptarán Ford y su concesionario?**

**Las piezas no se encuentran disponibles.** Ford Motor Company está trabajando para proporcionar las piezas para realizar esta reparación. Cuando la solución esté disponible, Ford Motor Company le notificará mediante correo para que programe una cita de servicio con su concesionario y así realizar las reparaciones sin costo alguno.

#### **¿Qué debe hacer?**

Para esta campaña de seguridad, Ford no ha emitido instrucciones de dejar manejar el vehículo. Una vez que haya una solución disponible, deberá comunicarse con su concesionario a fin de programar una cita para solucionar este problema lo más pronto posible.

Si aún no tiene un concesionario para realizar el servicio, puede acceder a [ford.com/support](https://ford.com/support) para conocer las direcciones de los concesionarios, ver mapas y obtener las instrucciones para llegar.

**¿Qué debe hacer?  
(continuación)**

Si continúa con dificultades para reparar su vehículo en un tiempo razonable o sin cargo, le sugerimos que escriba al Administrador, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 o bien que llame sin cargo a la línea directa de seguridad vehicular al 1-888-327-4236 (TTY: 1-888-275-9171) o visite [NHTSA.gov](https://www.nhtsa.gov). Referencia: Campaña de seguridad 25V829 de la NHTSA.

**Tenga presente que: La ley federal exige que los arrendadores de vehículos que reciban este aviso de campaña envíen una copia del mismo al arrendatario en un plazo de diez días.**

NOTA: Puede recibir información sobre las campañas y los programas de satisfacción del cliente a través de la aplicación Ford. La aplicación se puede descargar a través de App Store o Google Play. Adicionalmente, existen otras funciones como reserva de estacionamientos en determinados lugares, además de control de ciertas funciones en el vehículo (bloqueo o desbloqueo de puertas, arranque remoto) si así está equipado para permitir el control.

**¿Qué pasa si usted ya no es el propietario del vehículo?**

Si usted ya no es el propietario del vehículo y tiene la dirección del propietario actual, le solicitamos que le reenvíe esta carta.

Usted recibió este aviso porque las regulaciones del gobierno exigen el envío de notificaciones al propietario conocido más reciente del registro. Nuestros registros se basan principalmente en los datos de registro y título estatales, que indican que usted es el propietario o arrendatario actual.

Gracias por su atención en este asunto sumamente importante.

División de Servicio al Cliente