# Audi

# Technical Service Bulletin

#### 44 Steering wheel vibration and/or oscillation at low mileage - Repair Authorization

44 14 48 2030194/5 March 10, 2014. Supersedes Technical Service Bulletin Group 44 number 13-45 dated December 3, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A4, Q7	2014	All	Not Applicable	

#### Condition

REVISION HISTORY					
Revision	Date	Purpose			
5	-	Revised attachment			
4	12/03/2013	Revised Condition (Updated model information) Revised Service (Modified instructions)			
3	11/01/2013	Revised Service (Added step)			
2	09/26/2013	Revised header data (Updated vehicles)			
1	07/23/2012	Initial publication			

- Steering wheel vibration and/or steering wheel oscillation at a speed range of 55 80 mph (88 128 km/h) on vehicles with very low mileage or at PDI.
- The condition does not result in any handling concerns or loss of vehicle control.
- Vehicles have original factory-installed wheels and tires.
- · Affected vehicles include:
  - MY 2014 Q7
  - MY 2014 A4 with 18" tire

### **Technical Background**

Tire pressures on Audi vehicles are set to specified values in order to prevent flat spotting during the transportation process from various Audi plants to United States ports.

To closely monitor complaints of tire-related vibration at very low mileage, we are asking that you contact the Audi Technical Assistance Center (TAC) **before** performing any repairs on vehicles with this condition. This will assist us in diagnosing any potential issues with the condition noted above.

# Audi

# Technical Service Bulletin

#### **Production Solution**

Not applicable.

#### **Service**

1. Verify that the complaint matches the condition described at the top of this TSB. Complaints not related to the condition described in this TSB do not require TAC authorization.

Exclude vehicles if the following criteria are true:

- Any wheel or tire has been repaired (patches, plugs, rim repairs)
- Tires have damage (nails, gouges, large cuts)
- Wheels have damage (bent, gouges, cracks)
- · Tires have been replaced
- 2. Obtain and print road force values (RFV) DO NOT force match or balance tires.
- 3. Create a ticket using the TAC system in Elsa and complete the attached Tire Data Sheet. The data sheet must be completed before TAC is called. Attach the printed RFV documents from the balancer machine to the TAC ticket. Do not perform any repairs to the vehicle (balance, force match, remove weights, etc.).

## **Warranty**

This TSB is informational only and is not applicable to any Audi warranty.

## **Additional Information**

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

 TSB 2022563, Steering wheel shimmy, vibration, and/or oscillation (Only refer to the diagnosis section of this TSB. DO NOT repair the vehicle.)

All parts and service references provided in this TSB (2030194) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.



## Tire data sheet

## 1. Customer complaint

(e. g.: speed range, vibrations in acceleration/deceleration, vibration				
2. Vehicle data				
Make: VIN: Model type, description: Mileage with affected tires in km:		BA-ID accor Date of deliv	NA	
3. Tire data (in cold condi	tion)			
Tires arefitted at manufa Tire brand: Dimension:  Make of road force balancing mac	Tire type: Manufactur	di Original Parts  rer labeling:  st check date of re	(e.g.: AO, AOE	E, R01)
	front/left	front/right	rear/left	rear/right
DOT (four characters MM-YY)				
Tire pressure in bar				
Requested tire pressure according to filling pressure label	ok 🗌 n. ok 🗍	ok 🗌 n. ok 🔲	ok ☐ n. ok ☐	ok ☐ n. ok ☐
Tread depth in mm, outside/center/inside				
Attached weights  Balancing track inside/outside				
Damages at tire				
Damages at rim				
4. Tire data (in warm cond !!!Tires must be warmed prior to (Preliminary test drive of at least 1	o the roadforce b		/h for 15 miles) rear/left	rear/right
Tire pressure in bar				
RFV in lbs. (first harmonic)				

DO NOT ATTEMPT ANY REPAIRS (e.g. balance, force match) Attached this form to the TAC contact.