

February 2, 2016

03123 Version 1

Front Brake Noise

AFFECTED VEHICLES

Year	Model	Trim	VIN range
2016	ILX	ALL	ALL

SYMPTOM

The front brakes squeal when applied.

CORRECTIVE ACTION

Install new front brake discs and pads.

PARTS INFORMATION

Part Name	Part Number	Quantity
Front Brake Disc	45251-T2F-A81	2
Front Brake Pad Set	45022-T3R-A01	1

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
410101	Replace the front brake discs.	0.4 hr	00401	04212	16-004N	45251-TX4-A01
E	Replace the front brake pads.	0.3 hr				

Skill Level: Repair Technician

REPAIR PROCEDURE

1. Replace both front brake discs and brake pads. Refer to the service information.

END

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.