

[Next Unread Message](#)[View Message](#)

<b>Sent on</b>	03	20	2018	<b>Expires on</b>	04	02	2018
----------------	----	----	------	-------------------	----	----	------

<b>From</b>	Parts and Service Division
-------------	----------------------------

<b>Subject</b>	2017-2018 Civic Hatchback Windshield Washer Tank Leak
----------------	---

**PRIORITY/ACTION REQUIRED**

To: All Honda Service Managers/Advisors  
From: Technical Research & Support Group  
RE: Request for Parts: 2017-2018 Civic Hatchback Windshield Washer Tank Leak

This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda Motor Co., Inc. (AHM) is investigating certain 2017-2018 Civic Hatchbacks with a customer complaint of the windshield washer tank leaking. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. Leak must be confirmed.
2. First time & repeat complaint are accepted.
3. No repair has been attempted for this issue during current visit.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.