

**Subject: Engineering Information – Rattle Originating from Liftgate Trim Area**

*This PI has been revised to end the need for information from the field. Please discard PIE0404.*

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT5	2017	2017			All	All
GMC	Acadia (VIN N)	2017	2017			All	All

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.