

#### 44 Tire wear, Goodyear Eagle 285/45 R20 All Season

44 20 77 2048563/4 August 4, 2020. Supersedes Technical Service Bulletin Group 44 number 20-74 dated March 6, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017 - 2021	All	Not Applicable

#### **Condition**

REVISION HISTORY				
Revision	Date	Purpose		
4	-	Revised Required Parts and Tools (Updated Part Number)		
3	03/06/2020	Revised header (Added model years)		
2	10/20/2017	Revised Warranty (Added Diagnostic time)		

#### **Customer states:**

- The tire has abnormal wear on the outer edges.
- The tire pressure and the alignment are according to specifications.

## **Technical Background**

High ambient temperatures in connection with rough roads lead to increase wear only on the outer edges of the tire.

The following photograph shows an irregularity on the outer side and on the inner side of the tire (Figure 1). For this specific type of concern the tire must be replaced.





Figure 1. Irregularity on the outer side and on the inner side of the tire.

The following photograph shows a normal condition and the tire cannot be replaced (Figure 2).





Figure 2. Normal condition.

## **Production Solution**

Not applicable.



#### **Service**

#### If:

- The remaining tread depth is above 6.5mm (8/32<sup>nds</sup>").
- Wear on outer/inner edges is the same as Figure 1, then proceed as follows:
- 1. Replace all 4 tires with:
  - Pirelli Scorpion Verde 285/45 R20 112 H AOE1.
- 2. Upload pictures of the tires to DOC-IT for claim validation (4 pictures: one for each tire with visible marks FL, FR, RL, and RR).
- 3. Submit tires through Warranty Claim Portal on Dealer Tire website >> Workmanship and Materials >> tearing of tread.
- 4. If tires are similar to Figure 2, do not replace the tires and proceed with tire rotation.

**Tip:** Perform the repair only if the Customer concern is clearly confirmed, otherwise the claim will be debited.

### Warranty

Claim Type:	<ul> <li>110 up to 12 Months/12,000 Miles.</li> <li>If vehicle is outside any warranty this Technical Bulletin is information only.</li> </ul>		
Service Number:	4440		
Damage Code: 0010			
Labor Operations:	Check tread depth and wear on all tires (upload pictures to DOC-IT)	4440 9999	25 TU
	Remove 2 front wheels + tires	4405 2000	See SRT with associated operations
	Remove 2 rear wheels + tires	4405 2000	See SRT with associated operations
	Replace 2 front tires	4440 5650	See SRT with associated operations



	Replace 2 rear tires	4440 5650	See SRT with associated operations
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2048563/4		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## **Required Parts and Tools**

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.			
Part Number	Part Description	Quantity	
3445400 (Contact Dealer Tire)	Pirelli Scorpion Verde 285/45 R20 112 H AOE1	04 (If necessary)	
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA	

## **Additional Information**

All parts and service references provided in this TSB (2048563) are subject to change and/or removal.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.