

48 V battery G1/3 with P0A7F00 - The age limit of the hybrid/high-voltage battery module has been reached

Topic number	LI54.10-P-078888
Version	3
Function group	54.10 - Battery, power supply, voltage converter
Date	3/5/25
Validity	Model series 177, 118, 247 with equipment code B01
Reason for change	Validity

Complaint

The check engine light illuminates or the 48 V message is displayed in the instrument cluster

Cause

Fault code "P0A7F00" stored in the 48 V battery G1/3 and/or is current.

Remedy

Perform guided test for fault code "P0A7F00".

Important! To ensure a bus idle of 90 minutes is achieved, the vehicle should be locked and the key placed a minimum of 30 feet from the vehicle)

See SI82.85-P-0046A

Attachments		
File	Description	
si8285p0046a.pdf		

WIS-References		
Document number	Title	Note
SI82.85-P-0046A	Service Information: Restricting Remote Functions for maintenance and repair work	

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect

XENTRY Tips

is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms				
Overall vehicle > Power supply > Battery/On-board electrical system > Battery/on-board electrical system display message > Battery/Alternator - Serviced Required				
Overall vehicle > Power supply > High-voltage on-board electrical system > High-voltage battery > Display message				
Control unit/fault code				
Control unit			Fault text	
G1/3 - 48-V on-board electrical system battery (48 V LIB) (LIB48_177PT4)			P0A7F00 - The state of health limit of the hybrid/high-voltage battery module has been reached. _	
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			540HY	